

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 2670/PwD/DT 23-01-1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Educator District Sub-District
4. Classification of Building as specified in column 4 of the schedule with its approximate area and size
5. Period for which the certificate is issued 2023-2024
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Steenath A
Sri Sathya Sai vidyapeeth
Katalur (P.O), Koghikode.

SRI SADAN - 46.60 x 7.80 x 8.35
G.P & P.P - 5 classrooms, Lab & office

SRI SANDESH - 25.35 x 8.10 x 8.10
G.P & P.P - 4 x 2 = 8 classrooms

L.P BLOCK - 48.10 x 8.25 x 7.76
G.P & P.P - 6 x 2 = 12 classrooms

SRI SARASWATHI - 31.20 x 7.30 x 8.60
(G.P only - 5 classrooms)

NIL

- NO -

- YES -


Sound to conduct classes under normal wind & weather conditions

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, weather exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 31/05/23 and found to be fit / ~~not~~ to conduct classes, for the period one year (2023-2024) for the reasons stated above.

Place: Moodadi
Date: 31/05/23



[Signature]
ASSISTANT ENGINEER
For SRI SATHYA SAI TRUST KERALA

[Signature]
PRINCIPAL

SRI-SATHYA SAI VIDYAPEETH
SRI SAILAM, P.O. KATALUR
CALICUT DIST. PIN- 673 529

[Signature]
G. SATHEESH NAIR
CONVENER